

Code: WUN-XK125

TOOL FOR CLEANING FIBER OPTIC CONNECTORS **WUN-XK125** LC / MU, Ø 1.25 mm

The WUN-XK125 tool is used to clean the end face of the ferrule in fiber optic connectors. A special fabric removes any contaminants, and its antistatic properties prevent dust from settling again. The product is suitable both for cleaning connectors in adapters mounted individually and mounted in patch panels.



Application:	Ideal for removing dirt from optical components
Connector type:	LC / MU, Ø 1.25 mm
Weight:	0.02 kg
Dimensions:	184 x 17 x 17 mm